


S/N 10/577339

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant:	XIAO	Patent No:	7,392,770
Serial No.:	10/577339	Issue Date:	July 1, 2008
Filed:	April 27, 2006	Docket No.:	09548.1028USWO
Title:	A COOLING SYSTEM OF AN ENGINE FOR THE INSIDE OF A GENERATOR		

CERTIFICATE OF TRANSMISSION
I hereby certify that this paper is being transmitted by EFS Web to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on February 4, 2009.

By: 
Name: Lauren Sindt

REQUEST FOR CERTIFICATE OF CORRECTION

Attn: Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, Virginia 22313-1450


Dear Sir:

It is requested that a Certificate of Correction be issued correcting printing errors appearing in the above-identified United States patent. A copy of the text of the Certificate in the suggested form is attached.

Issuance of the Certificate of Correction would neither expand nor contract the scope of the claims, and re-examination is not required.


As none of the errors are the Patentees' mistake, it is believed that no fee is due.

Respectfully submitted,



HAMRE, SCHUMANN, MUELLER &
LARSON, P.C.
P.O. Box 2902
Minneapolis, MN 55402-0902
(612) 455-3800

Dated: February 4, 2009

By: 
Rong Yang
Lim. Recognition No.: L0279
CY/lS

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTIONPage 1 of 1

PATENT NO. : 7,392,770 B2

APPLICATION NO.: 10/577339

ISSUE DATE : July 1, 2008

INVENTOR(S) : Henglin Xiao

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2, line 1: "technology in the art the" should read --technology in the art, the--.

Column 3, line 4: "said tool air suction hood" should read --said cool air suction hood--.

Column 4, line 10: "manufacturing cost The engine" should read --manufacturing cost. The engine--.

Column 4, line 49: "a scaling ring sealing a connection" should read --a sealing ring sealing a connection--.

Column 6, line 9 (claim 7): "magnet motor the cool" should read --magnet motor, the cool--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.